

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,968,398 B2
DATED : November 22, 2005
INVENTOR(S) : Davis et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 7,


Line 58, should read -- through platform firmware, wherein the step of dynami- --.

Column 8,

Line 21, should read -- routing said virtual resource address includes mapping said --.

Signed and Sealed this

Twenty-fourth Day of January, 2006



JON W. DUDAS
Director of the United States Patent and Trademark Office